

# CORRESPONDANCES DN / POUCES



DN6	1/8"	DN100	4"
DN8	1/4"	DN125	5"
DN10	3/8"	DN150	6"
DN15	1/2"	DN200	8"
DN20	3/4"	DN250	10"
DN25	1"	DN300	12"
DN32	1"1/4	DN350	14"
DN40	1"1/2	DN400	16"
DN50	2"	DN450	18"
DN65	2"1/2	DN500	20"
DN80	3"	DN600	24"
		DN700	28"
		DN800	32"
		DN1000	40"



**MÉMOS** de la ROBINETTERIE  
INDUSTRIELLE

# CORRESPONDANCES DN / RACCORDS GAZ



DN8	1/4"	8-13
DN10	3/8"	12-17
DN15	1/2"	15-21
DN20	3/4"	20-27
DN25	1"	26-34
DN32	1"1/4	33-42
DN40	1"1/2	40-49
DN50	2"	50-60
DN65	2"1/2	66-76
DN80	3"	80-90
DN100	4"	102-114
DN125	5"	127-140
DN150	6"	152-165

**MÉMOS** de la ROBINETTERIE  
INDUSTRIELLE